

Reclamation Inspection

01/09/2017

Operator: Atlas Resources LLC

Location ID: 421361

Phillips County, CO

SWNW Section 34 T9N R43W

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO

Department of Natural Resources



ATLAS ROCKIES LLC
BLACK RAVEN ENERGY-10203
ENNINGA 943-21-23
NESW, SEC.21-T9N-R43W
PHILLIPS COUNTY, CO
05-095-06306
EMERGENCY 911 OR 303-308-1330

01.09.2017 12:02

Figure 1: Photo of well.



Figure 2: Photo taken from the northeast end of the location, facing south. Photo shows interim and project areas.



Figure 3: Photo taken from the northeast end of the location, facing west Photo shows interim and project areas.



Figure 4: Photo taken from the northwest end of the location, facing east. Photo shows interim and project areas.



Figure 5: Photo taken from the northwest end of the location, facing south. Photo shows interim and project areas.



Figure 6: Photo taken from the southwest end of the location, facing north. Photo shows interim and project areas.



Figure 7: Photo taken from the southwest end of the location, facing east. Photo shows interim and project areas.



Figure 8: Photo taken from the southeast end of the location, facing west. Photo shows interim and project areas.



Figure 9: Photo taken from the southeast end of the location, facing north. Photo shows interim and project areas.



095-06306
1/9/17
Dist #1

01.09.2017 12:35

Figure 10: Photo taken from the southeast end of the interim area. Photo shows disturbance quadrat #1



095-06306
1/9/17
Dist #2

01.09.2017 12:36

Figure 11: Photo taken from the north end of the interim area. Photo shows disturbance quadrat #2



Figure 12: Photo taken from the west end of the interim area. Photo shows disturbance quadrat #3



Figure 13: Photo taken from the reference area, west of the location. Photo shows Reference quadrat #1



Figure 14: Photo taken from the reference area, north of the location. Photo shows Reference quadrat #2



Figure 15: Photo taken at the well head. Photo shows discolored soil. Discolored soil appears to be being transported away from well via stormwater. Soil will need to be cleaned. 6 foot measuring stick for reference.