

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/12/2017

Submitted Date:

01/12/2017

Document Number:

680401106**FIELD INSPECTION FORM**
 Loc ID 417723 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 10493Name of Operator: ALANCO ENERGY SERVICES INCAddress: 7950 E ACOMA DRIVE STE 111City: SCOTTDALE State: AZ Zip: 85260**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments6 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
		COGCC_Engineering@state.co.us	
Carlson, John	(480) 505-4869	john@alanco.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
417724	WELL	WO	03/14/2011	LO	077-10096	Deer Creek SWD 1	TA

**General Comment:**

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action		Date:	
Type	Main		
comment:			
Corrective Action		Date:	
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Sign not posted or information incomplete. No sign on wellhead (Rule 210.b.). Photo attached		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	04/07/2017
Emergency Contact Number:			
Comment:	No Emergency Contact Number.		
Corrective Action:	Install sign to comply with Rule 210.	Date:	02/24/2017
<b>Good Housekeeping:</b>			
Type	TRASH		
Comment:	Trash and debris around location		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	01/27/2017
Type	WEEDS		
Comment:	Weeds grown up around wellhead.		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	01/27/2017
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment, pipe and junk equipment around location.		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	02/24/2017
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	LOCATION		
Comment:	5 strand barb wire		
Corrective Action:		Date:	
<b>Venting:</b>			

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 417724 Type: WELL API Number: 077-10096 Status: WO Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Well Located on Deer Creek Solid Waste Facility (CDPHE).  
COGCC UIC Class 2 disposal well permit application denied 6/26/2011 (Doc#2617226).  
EPA UIC Class 1 disposal well permit application denied 2/19/2014 (Doc#2089861).  
Last MIT 10/30/2013. Next MIT due by 10/30/2018.  
No Form 4 or other form approved by the Director for extension is on file as required by Rule 319.b.1 and 319.b.3.

Rule 319.b.1 states "....If an operator requests temporary abandonment status in excess of six months the operator shall state the reason for requesting such extension and state plans for future operation. A Sundry Notice, Form 4, or other form approved by the Director, shall be submitted annually stating the method the well is closed to the atmosphere and plans for future operation..."

Rule 319.b.3 states "....A well which has ceased production or injection and is incapable of production or injection shall be abandoned within six months thereafter unless the well passes a successful mechanical integrity test per Rule 326, and the time is extended by the Director upon application by the owner...."

Corrective Action: Contact COGCC\_Engineering@state.co.us with resolution plan.Date: 01/27/2017

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680401107	077-10096 Alanco Energy - Deer Creek SWD#1	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4050659">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4050659</a>