

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/06/2017

Submitted Date:

01/06/2017

Document Number:

674901415

FIELD INSPECTION FORM

Loc ID 325858 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10254
 Name of Operator: RED MESA HOLDINGS/O&G LLC
 Address: 5619 DTC PARKWAY - STE 800
 City: GREENWOOD State: CO Zip: 80111

Findings:

- 9 Number of Comments
3 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
St John, William (Cal)		cal.stjohn@state.co.us	
Roy, Catherine		catherine.roy@state.co.us	
Andrews, Dave		david.andrews@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	
Weems, Mark		mark.weems@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215480	WELL	PR	01/05/2009	OW	067-07085	TALBOT-WIDEMAN 13-1	EI

General Comment:

On January 6, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Red Mesa Holdings LLC Talbot-Wideman #13-1. This field inspection resulted from complaint #200440902. For the most recent field inspection report of this facility, please refer to document #668402746, which includes an attached FLIR camera video of the well head. During this site visit, it was observed that conditions at this location were similar to the photos attached to inspection document #674601624 conducted on 3/26/15. The location was snow covered during this field inspection.

Location					
Overall Good: <input checked="" type="checkbox"/>					
Signs/Marker:					
Type	OTHER				
Comment:	Unlabeled propane tank on east side of location.				
Corrective Action:	Install sign to comply with Rule 210.d. Corrective action date taken from inspection document #674601624.				Date: 05/04/2015
Type	WELLHEAD				
Comment:	Location sign mounted to guard fencing for pump jack.				
Corrective Action:					Date:
Emergency Contact Number:					
Comment:					Date: _____
Corrective Action:					Date: _____
Good Housekeeping:					
Type	UNUSED EQUIPMENT				
Comment:	Disconnected propane tank on east side of location.				
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details. Corrective action date taken from inspection document #674601624.				Date: 05/04/2015
Overall Good: <input type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Fencing/:					
Type	PUMP JACK				
Comment:	Guard fencing present.				
Corrective Action:					Date:
Equipment:					
					corrective date
Type: Pump Jack	# 1				
Comment:	Stained soils beneath prime mover.				
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. Corrective action date taken from inspection document #674601624.				Date: 05/04/2015
Type: Deadman # & Marked	# 4				
Comment:					
Corrective Action:					Date:
Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	100 BBLS	STEEL AST		37.102771,-108.104006
Comment:	Label and placard are peeling off of tank. 100 bbl. AST is labeled "WNR-11709 11-10 3/4 0-11 3/4".				
Corrective Action:					Date:

Paint				
Condition	Adequate			
Other (Content)				
Other (Capacity)				
Other (Type)				
Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities

Facility ID: 215480 Type: WELL API Number: 067-07085 Status: PR Insp. Status: EI

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Spill Response	Pass	Spill kit near AST.

Comment: Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>On January 6, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Red Mesa Holdings LLC Talbot-Wideman #13-1. This field inspection resulted from complaint #200440902. For the most recent field inspection report of this facility, please refer to document #668402746, which includes an attached FLIR camera video of the well head. During this site visit, it was observed that conditions at this location were similar to the photos attached to inspection document #674601624 conducted on 3/26/15. The location was snow covered during this field inspection. Stained soils, noted in inspection document #674601624, were present beneath the prime mover during this field inspection. An unused propane tank, noted on previous inspections, is present on the east side of the location. The label and placard on the 100 bbl. AST is peeling off of the tank.</p>	hughesj	01/06/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401179445	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4046057
674901416	Talbot-Wideman #13-1 pump jack.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4046050
674901417	Stained soil beneath prime mover.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4046051
674901418	Talbot-Wideman #13-1 well head.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4046052
674901419	Unused propane tank on east side of location.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4046053
674901420	100 bbl. AST.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4046054