



photo 1: Facing east at the beginning of the access road which is not included in the variance request.



photo 2: Facing east along the access road.



photo 3: The soils along the access road are compacted and vegetation is not adequately establishing.



photo 4: Facing back toward the west along the access road.



photo 5: Facing east along the access road.



photo 6: Facing east toward the location which has a perimeter fence.



photo 7: Facing east toward the location.



photo 8: There are areas of the location which have compacted soils.



photo 9: There is desirable vegetation establishing at the center of the location.



photo 10: Facing toward the north side of the location.



photo 11: North side of the location facing west. There is predominantly undesirable vegetation growth (Russian thistle) in this area.



photo 12: Facing north toward the surrounding undisturbed pasture.