

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/05/2017

Submitted Date:

01/13/2017

Document Number:

674901441

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
306898 _____ Hughes, Jim _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 53255
 Name of Operator: MARALEX RESOURCES, INC
 Address: P O BOX 338
 City: IGNACIO State: CO Zip: 81137

Findings:

- 8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
O'Hare, Mickey	(970) 563-4000/ (719) 429-3529	amohare@maralexinc.com	President
Tahmahkera, Kerry	(970) 563-4000	maralextech@gmail.com	All Inspections
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275103	WELL	PR	08/12/2014	GW	067-08998	CORY JACK 33-7-11 2	EI

General Comment:

On January 5, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Maralex Resources Cory Jack 33-7-11 #2. For the most recent field inspection report of this facility, please refer to document #680600644.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Location sign mounted to pump jack.		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Label and placard on chemical injection container and lube oil container.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PUMP JACK		
Comment:	Partial sound wall on south side of pump jack.		
Corrective Action:		Date:	

Equipment:

Type					corrective date
Type: Deadman # & Marked	# 4				
Comment:					
Corrective Action:		Date:			
Type: Pump Jack	# 1				
Comment:					
Corrective Action:		Date:			
Type: Gas Meter Run	# 1				
Comment:					
Corrective Action:		Date:			
Type: Horizontal Heated Separator	# 1				
Comment:					
Corrective Action:		Date:			

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 275103 Type: WELL API Number: 067-08998 Status: PR Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	

Comment: Secondary containment for lube oil container and chemical injection system container. The expanded metal wildlife screen in the secondary containment for the chemical injection system is submerged in fluids.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On January 5, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Maralex Resources Cory Jack 33-7-11 #2. For the most recent field inspection report of this facility, please refer to document #680600644. During this inspection it was observed that the expanded metal wildlife screen in the secondary containment for the chemical injection system is submerged in fluids.</p>	hughesj	01/13/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674901442	Cory Jack 33-7-11 #2 pump jack and well head.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4051525
674901443	Partial sound wall and location BMP.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4051526
674901444	Expanded metal wildlife screen is submerged.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4051527