

Reclamation and Stormwater Inspection

01/18/2017

Operator: Foundation Energy #10112

Location ID: 330865

Weld County, CO

NENW Section 36 T6N R61W

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO

Department of Natural Resources



Figure 2: Photo taken from the location, facing west. Photo of pump-jack and well. Photo shows sign missing at wellhead.



Figure 3: Photo taken from the location, facing east. Photo shows two tanks on the location. Photo also shows area where access road enters the location (right of photo).



Figure 4: Photo taken from the southwest corner of the tank battery, facing east. Photo shows the earthen berm used as secondary containment is insufficient and unmaintained.



Figure 5: Photo taken from the southwest corner of the tank battery, facing north. Photo shows the earthen berm as secondary containment is insufficient and unmaintained.



Figure 6: Photo taken from the tank battery, facing east. Photo shows sign has deteriorated in such a manner that the operator contact information is illegible.



Figure 7: Photo taken from the northeast end of the location, facing southeast. Photo shows skim pit.



Figure 8: Photo taken from the northeast corner of the location, facing south. Photo shows location and interim area. Note road passing through area of location.



Figure 9: Photo taken from the northwest corner of the location, facing southwest. Photo shows the interim reclamation area. Note vegetation seen in photo predominantly undesirable weedy species such as russian thistle.



Figure 10: Photo taken from the northwest corner of the location, facing west. Photo shows the interim reclamation area. Note vegetation seen in photo predominantly undesirable weedy species such as russian thistle



Figure 11: Photo taken from the northwest corner of the location. Photo shows square iron tubing being stored. This needs to be removed and properly stored/disposed.



Figure 12: Photo taken from the northwest corner of the location, facing south. Photo shows areas not needed for production have not been reclaimed, including re-contouring.



Figure 13: Photo taken from the southwest corner of the location, facing east. Photo shows stormwater ditch located on the western and southern perimeter of the location.



Figure 14: Photo taken from the southwest corner of the location, facing north. Photo shows stormwater ditch located on the western and southern perimeter of the location. Note erosion occurring on slope of the location to the right of the photos (yellow arrow). Photo also shows location has not been recontoured.



Figure 15: Photo taken from the southwest corner of the location, facing north. Photo shows large areas of the location that do not appear to be needed for production have not been reclaimed. Note vegetation on location predominantly undesirable weedy species such as russian thistle. Photo also shows location has not been recontoured.



Figure 16: Photo taken from the southwest corner of the location, facing northeast. Photo shows large areas of the location that do not appear to be needed for production have not been reclaimed. Note vegetation on location predominantly undesirable weedy species such as russian thistle.




Figure 17: Photo taken from the southwest corner of the location, facing east. Photo shows large areas of the location that do not appear to be needed for production have not been reclaimed. Note vegetation on location predominantly undesirable weedy species such as russian thistle. Photo also shows location has not been recontoured.



Figure 18: Photo taken from the south end of the location, facing east. Photo shows areas of the location experiencing degradation due to erosion.



Figure 19: Photo taken from the southwest end of the location. Photo shows vegetation over the location. Note vegetation predominantly undesirable weedy species such as russian thistle.



160673
113948

01.17.2017 11:33

Figure 20: Photo taken from the southern tank. Photo shows a placard has been placed on the tank since inspection doc. #684901990. However tank missing 1) Name of operator, 2) Operator's emergency contact number and 3) Tank capacity.



Figure 21: Photo taken from the northern tank. Photo shows a placard has been placed on the tank since inspection doc. #684901990. However tank missing 1) Name of operator, 2) Operator's emergency contact number and 3) Tank capacity.



Figure 22: Photo taken from skim pit on the northeast end of the location, facing west.