

# Reclamation and Stormwater Inspection

01/18/2017

Operator: Bonanza Creek #8960

Location ID: 437240

Weld County, CO

NWNE Section 12 T5N R61W

Aaron Trujillo

Reclamation Specialist

COGCC



**COLORADO**

Department of Natural Resources



**Figure 1:** Photo taken from the pump jack/well. Photo shows sign at well.



**Figure 2:** Photo taken from the north end of the location, facing north. Photo shows below ground 60 bbl “maintenance vault”



**Figure 3:** Photo taken from the northwest end of the location, facing south. Photo shows interim and productions areas.



**Figure 4:** Photo taken from the northwest end of the location, facing southeast. Photo shows interim and productions areas.



**Figure 5:** Photo taken from the northwest end of the location, facing east. Photo shows interim and productions areas.



**Figure 6:** Photo taken from the northeast end of the location, facing west. Photo shows interim and productions areas.



**Figure 7:** Photo taken from the northeast end of the location, facing west. Photo shows interim areas. Note topsoil stockpile center of photo.



**Figure 8:** Photo taken from the east end of the location, facing south. Photo of soil stockpile.



**Figure 9:** Photo taken from the soil stockpile on the east end of the location, facing southwest. Photo shows interim area.



**Figure 10:** Photo taken from the soil stockpile on the east end of the location, facing southwest. Photo shows interim area and production area.



01.17.2017 12:48

**Figure 11:** Photo taken from the soil stockpile on the east end of the location, facing northwest. Photo shows interim area and production area.



**Figure 12:** Photo taken from the soil stockpile on the east end of the location, facing north. Photo shows interim area.



**Figure 13:** Photo taken from the southeast corner of the location, facing west. Photo shows interim and production areas.



**Figure 14:** Photo taken from the southeast corner of the location, facing northwest. Photo shows interim and production areas.



**Figure 15:** Photo taken from the southeast corner of the location, facing north. Photo shows interim areas.



**Figure 16:** Photo taken from the interim area, east of the well, facing north. Photo shows large areas of the interim area where gravel remains and area remains unvegetated.



**Figure 17:** Photo taken from the interim area, east of the well. Photo shows large areas of the interim area where gravel remains and area remains unvegetated. 6 foot measuring stick for reference.



**Figure 18:** Photo taken from the interim area, east of the well. Photo shows large areas of the interim area where gravel remains and area remains unvegetated. 6 foot measuring stick for reference.



**Figure 19:** Photo taken from the southwest end of the location, facing north. Photo shows vegetation over the interim area.



**Figure 20:** Photo taken from the southwest end of the location, facing east. Photo shows vegetation over the interim area.



**Figure 21:** Photo taken from the southwest end of the production area, facing east. Photo shows where the production area ends and where the interim area begins on the south end of the location.