



**photo 1:** Facing west along the former access road.



**photo 2:** Facing north toward the location. The vegetation has not adequately established in this area.



**photo 3:** The soils seemed to be compacted.



**photo 4:** South side of the location facing north. The vegetation has not adequately established in this area.