

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/19/2017

Submitted Date:

01/19/2017

Document Number:

685501763**FIELD INSPECTION FORM**
 Loc ID 323205 Inspector Name: MONTOYA, JOHN On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 46290Name of Operator: K P KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
244914	WELL	PR	10/22/2012	GW	123-12709	JORDAN 34-4	SI

General Comment:

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	NO WELL SIGN AT WELLHEAD		
Corrective Action:	Install sign to comply with Rule 210.a.	Date:	02/02/2017

Emergency Contact Number:			
Comment:	OK, EMERGENCY NUMBER ON BATTERY SIGN		
Corrective Action:		Date:	

Overall Good: ☒

Spills:				
Type	Area	Volume		
Crude Oil	WELLHEAD	<= 1 bbl		
Comment:	SOILED DIRT AROUND WELLHEAD			
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.			Date: 02/02/2017
Crude Oil	Separator	<= 1 bbl		
Comment:	STAINED SOIL INSIDE SEP HOUSE FROM LEAKING 2" VALVE			
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.			Date: 02/02/2017

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	2" PIPE FENCE SE CORNER N40.00305 W-104.38654		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:		
Type		
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected FacilitiesFacility ID: 244914 Type: WELL API Number: 123-12709 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: _____

Corrective Action: _____

Date: _____

COGCC Comments

Comment

User

Date

INTERMITTER CONTROLLER ON WELLHEAD
DOCUMENT # 685501095, DATED 10/26/16, STAINED SOIL NOT CLEANED UP
AROUND WELLHEAD, STAINED SOIL INSIDE SEP HOUSE FROM 2" VALVE LEAKING

montoyaj

01/19/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685501764	STAINED SOIL LEAKING 2" VALVE	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4055368
685501765	FITTING LEAKING BY 2" VALVE	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4055369
685501766	STAINED SOIL AT WELLHEAD	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4055370
685501767	STEM ON N=MASTER VALVE LEAKING ON GROUND	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4055371
685501768	NO WELL SIGN	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4055372