

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/19/2017

Submitted Date:

01/19/2017

Document Number:

685501770**FIELD INSPECTION FORM**

Loc ID 323005 Inspector Name: MONTOYA, JOHN On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 46290Name of Operator: K P KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
244626	WELL	PR	10/10/1985	GW	123-12421	Jordan #34-2	PR

General Comment:

Location

Lease Road:			
Type	Main		
comment:			
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: OK

Corrective Action:

Date: _____

Overall Good: ☒

Spills:					
Type	Area	Volume			
Crude Oil	Separator	<= 1 bbl			
Comment:	2" VALVES LEAKING OIL ON EAST SIDE OF SEPERATOR, AND SEPERATOR NEEDS TO BE WASHED OUT OIL LEAKING ALL OVER INSIDE SEPERATOR				
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.				Date: 02/02/2017

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	2" PIPE FENCE		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	#		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 244626 Type: WELL API Number: 123-12421 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment

User

Date

INTERMITTER CONTROLLER ON WELLHEAD
DOCUMENT # 685500996, DATED 10/13/16, NONE OF THE WORK HAS NOT BEEN
COMPLETED FROM LAST INSPECTION

montoyaj

01/19/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685501771	SOILED DIRT AT SEPERATOR	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4055373
685501772	2" VALVE LEAKING	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4055374
685501773	2" VALVE NEEDS REPAIRED LEAKING	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4055375
685501774	UNIT NEEDS CLEANED OUT	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4055376
685501775	UNIT NEEDS CLEANED OUT	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4055377