

Reclamation Inspection

01/19/2017

Operator: Burlington Resources/ConocoPhillips

Location ID: 436726

Adams County, CO

NENE Section 35 T3S R65W

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO

Department of Natural Resources



ConocoPhillips
RESERVE 3-65-34-35-1H
CA# COC77105
NE/NE SEC. 35 TWP:3S RNG:65W
ADAMS COUNTY, COLORADO ELEVATION, 5506'
-ACCESS LOCATION FROM HUDSON RD.
-24 HR CONOCOPHILLIPS CONTACT: 1-855-595-8258
LOCAL EMERGENCY SERVICES: 911 NO SMOKING

DANGER
DO NOT ENTER
AUTHORIZED
PERSONNEL ONLY

01.19.2017 11:21

Figure 1: Photo of sign at pump jack.



Figure 2: Photo taken from the southeast end of the location, facing north. Photo production and interim areas.



Figure 3: Photo taken from the southeast end of the location, facing west. Photo production and interim areas.



Figure 4: Photo taken from the south end of the location, facing west. Photo shows the topsoil stockpile.



Figure 5: Photo taken from the south end of the location. Photo shows wattles used as stormwater and sediment control BMPs no longer in proper functioning condition.



Figure 6: Photo taken from the southwest end of the location, facing east. Photo production and interim areas.



Figure 7: Photo taken from the southwest end of the location, facing east. Photo production and interim areas. Note, designated final land use cropland, interim areas have not been returned to it's final land use.



Figure 8: Photo taken from the west end of the location, facing northeast. Photo production and interim areas. Note, designated final land use cropland, interim areas have not been returned to it's final land use.



Figure 9: Photo taken from the west end of the location, facing east. Photo shows large areas of the location that do not appear to be necessary for production activities.



Figure 10: Photo taken from the west end of the location, facing south. Photo production and interim areas. Note, designated final land use cropland, interim areas have not been returned to it's final land use. Photo also shows large areas of the location that do not appear to be necessary for production activities.



Figure 11: Photo taken from the northwest end of the location, facing south. Photo shows large areas of the location that do not appear to be necessary for production activities.



Figure 12: Photo taken from the north end of the location. Photo shows wattles used as stormwater and sediment control BMPs no longer in proper functioning condition.



Figure 13: Photo taken from the northeast end of the location, facing northeast. Photo shows sediment trap.



Figure 14: Photo taken from the northeast end of the location, next to sediment trap. Photo shows wattles used as stormwater and sediment control BMPs no longer in proper functioning condition.



Figure 15: Photo taken from the northwest corner of the location, facing west. Photo shows interim and project areas.



Figure 16: Photo taken from the northwest corner of the location, facing south. Photo shows interim and project areas.



Figure 17: Photo taken from the east end of the location at access road. Photo shows culvert.



Figure 18: Photo taken from the east end of the location at access road. Photo shows culvert



Figure 19: Photo taken from the access road near the country road, east .Photo shows culvert and stormwater BMPs



Figure 20: Photo taken from the access road near the country road, east .Photo shows culvert and stormwater BMPs