

Stormwater Inspection



Photo 1. Photo taken from the northwest location, facing South. Insufficient BMP installed around perimeter of location (i.e., swallow ditch) with no, to minimal unconsolidated berm. BMP appears to be in the same condition as the previous inspection.

Stormwater Inspection



Photo 2. Photo taken from the southwest location, facing East. Insufficient BMP installed around perimeter of location (i.e., swallow ditch) with no, to minimal unconsolidated berm. BMP appears to be in the same condition as the previous inspection.

Stormwater Inspection



Photo 3. Photo taken from the southern location, facing East. Insufficient BMP installed around perimeter of location (i.e., swallow ditch) with no, to minimal unconsolidated berm. BMP appears to be in the same condition as the previous inspection.

Stormwater Inspection



Photo 4. Photo taken from the southeast location, facing North. Insufficient BMP installed around perimeter of location (i.e., swallow ditch) with no, to minimal unconsolidated berm. BMP appears to be in the same condition as the previous inspection.

Stormwater Inspection



Photo 5. Photo taken from the northeast location, facing South. Insufficient BMP installed around perimeter of location (i.e., swallow ditch) with no, to minimal unconsolidated berm. BMP appears to be in the same condition as the previous inspection.