

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
01/19/2017
Submitted Date:
01/24/2017
Document Number:
682401728

FIELD INSPECTION FORM

Loc ID 331598 Inspector Name: Binschus, Chris On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------------------|---------|
| | | COGCCinspections@anadarko.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 444022 | WELL | XX | 11/20/2015 | LO | 123-42454 | GUEST 28N-25HZ | CI |
| 444023 | WELL | XX | 11/20/2015 | LO | 123-42455 | GUEST 3C-25HZ | CI |
| 444024 | WELL | XX | 11/20/2015 | LO | 123-42456 | GUEST 29N-25HZ | CI |
| 444025 | WELL | XX | 11/20/2015 | LO | 123-42457 | GUEST 3N-12HZ | CI |
| 444026 | WELL | XX | 11/20/2015 | LO | 123-42458 | GUEST 29N-12HZ | CI |
| 444030 | WELL | XX | 11/20/2015 | LO | 123-42462 | GUEST 28C-12HZ | CI |

General Comment:
This is a construction and stormwater inspection in response to Form 42- Notice of construction- Document #401175528.

Location Construction

Location ID: 331598 CDP: _____

Comment: Topsoil has been salvaged, stored, and temporarily stabilized (i.e., tracked) along the southern perimeter location. Per Rule 1002, topsoil shall be stabilized and protected from degradation due to wind and water erosion. BMPs to prevent weed establishment and to maintain soil microbial activity shall be implemented.

Corrective Action: _____ Date: _____

Form 2A COAs:

Comment: _____

Corrective Action: _____ Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____ Date: _____

Stormwater:

| | | | |
|--------------|---------|------------|---------|
| Erosion BMPs | Present | Other BMPs | Present |
|--------------|---------|------------|---------|

| | | | |
|-------|-----|--|--|
| BERMS | Yes | | |
|-------|-----|--|--|

Comments: Erosion BMPs:

Other BMPs:

Corrective Action: _____ Date: _____

| | | | |
|-----------------|-----|--|--|
| RETENTION PONDS | Yes | | |
|-----------------|-----|--|--|

Comments: Erosion BMPs: **Two (2) sediment traps are IN-PROCESS of being built along the southeast and northeast perimeter of location.**

Other BMPs:

Corrective Action: _____ Date: _____

| | | | |
|---------|-----|--|--|
| DITCHES | Yes | | |
|---------|-----|--|--|

Comments: Erosion BMPs:

Other BMPs:

Corrective Action: _____ Date: _____

Comment:

Corrective Action: **Date:** _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities

| | | | | |
|----------------------------|-------------------|------------------------------|-------------------|-------------------------|
| Facility ID: <u>444022</u> | Type: <u>WELL</u> | API Number: <u>123-42454</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>444023</u> | Type: <u>WELL</u> | API Number: <u>123-42455</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>444024</u> | Type: <u>WELL</u> | API Number: <u>123-42456</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>444025</u> | Type: <u>WELL</u> | API Number: <u>123-42457</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>444026</u> | Type: <u>WELL</u> | API Number: <u>123-42458</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>444030</u> | Type: <u>WELL</u> | API Number: <u>123-42462</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |

COGCC Comments

| Comment | User | Date |
|--|-----------|------------|
| Follow up inspection(s) will proceed while construction of location is IN-PROCESS. | binschusc | 01/24/2017 |
| Refer to attached photos in Document #682401729. | | |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 682401729 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4058347 |