

Construction and Stormwater Inspection- Overview



Google Earth aerial photo taken 10/9/2015 of the ACCO TERRA STATE 18-36 location. Total area of 4.94 acres was mapped on 1/19/2017 using a Trimble Juno 3B handheld device. Perimeter of location mapped and highlighted in red.

Construction and Stormwater Inspection



Photo 1. Photo taken from the entrance of location on the eastside of the access road, facing South. Ditch and berm BMP installed around the entire perimeter of the location. Sediment trap has been installed with a stabilized outlet.

Construction and Stormwater Inspection



Photo 2. Photo taken from the entrance of location on the westside of the access road, facing West. Ditch and berm BMP installed around the entire perimeter of the location. Sediment trap has been installed with a stabilized outlet.

Construction and Stormwater Inspection



Photo 3. Photo taken from the northern location, facing West, towards the topsoil stockpile. Topsoil stockpile appears steep on the north-facing side and would be difficult for perennial vegetative growth to establish for stabilization. May consider re-contouring when conditions are suitable (i.e., after winter).

Construction and Stormwater Inspection



Photo 4. Photo taken from the western location, facing South. Ditch and berm BMP installed around the entire perimeter of the location.

Construction and Stormwater Inspection



Photo 5. Photo taken from the southwest location, facing East. Ditch and berm BMP installed around the entire perimeter of the location.

Construction and Stormwater Inspection



Photo 6. Photo taken from the southeast location, facing North. Ditch and berm BMP installed around the entire perimeter of the location. Sediment trap has been installed with a stabilized outlet.