

Photo#1:
Access Road into Location



Photo#2:
Access Road exiting Location to HWY 13



January 20, 2017

Inspection Photos: Kerr McGee PA North Rifle

Photo#3:
View North over Location Center



Photo#4:
View South over Location Center



Photo#5:

View East over Location Center



Photo#6:

View West over Location Center



Photo#7:
Area of Thistle in NW Corner.



Photo#8:
Remnants of Annual Weeds in NE section.



Photo#9:

Site does not appear to have been re-contoured.



Photo#10:

Drainage that enters Location from NW

