

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/13/2017

Submitted Date:

01/18/2017

Document Number:

682401700**FIELD INSPECTION FORM**

| Loc ID<br>336152  | Inspector Name:<br>Binschus, Chris | On-Site Inspection <input type="checkbox"/> | 2A Doc Num: _____ | <b>Status Summary:</b><br><input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION<br><input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED<br><input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED<br><br><b>Findings:</b><br>2 Number of Comments<br>1 Number of Corrective Actions<br><input checked="" type="checkbox"/> Corrective Action Response Requested |           |               |             |            |         |                               |             |        |      |    |            |    |           |              |    |
|---|------------------------------------|---|-------------------|---|-----------|---------------|-------------|------------|---------|-------------------------------|-------------|--------|------|----|------------|----|-----------|--------------|----|
| <b>Operator Information:</b><br>OGCC Operator Number: <u>47120</u><br>Name of Operator: <u>KERR MCGEE OIL &amp; GAS ONSHORE LP</u><br>Address: <u>P O BOX 173779</u><br>City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80217-</u>   |                                    |   |                   |   |           |               |             |            |         |                               |             |        |      |    |            |    |           |              |    |
| <b>Contact Information:</b><br><table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> </thead> <tbody> <tr> <td>,</td> <td></td> <td>COGCCinspections@anadarko.com</td> <td></td> </tr> </tbody> </table>   |                                    |   |                   | Contact Name  | Phone     | Email         | Comment     | ,          |         | COGCCinspections@anadarko.com |             |        |      |    |            |    |           |              |    |
| Contact Name  | Phone                              | Email                                       | Comment           |   |           |               |             |            |         |                               |             |        |      |    |            |    |           |              |    |
| ,   |                                    | COGCCinspections@anadarko.com               |                   |   |           |               |             |            |         |                               |             |        |      |    |            |    |           |              |    |
| <b>Inspected Facilities:</b><br><table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> </thead> <tbody> <tr> <td>295914</td> <td>WELL</td> <td>PR</td> <td>10/18/2010</td> <td>OW</td> <td>123-25854</td> <td>TURNER 21-34</td> <td>RI</td> </tr> </tbody> </table> |                                    |   |                   | Facility ID   | Type      | Status        | Status Date | Well Class | API Num | Facility Name                 | Insp Status | 295914 | WELL | PR | 10/18/2010 | OW | 123-25854 | TURNER 21-34 | RI |
| Facility ID   | Type                               | Status                                      | Status Date       | Well Class  | API Num   | Facility Name | Insp Status |            |         |                               |             |        |      |    |            |    |           |              |    |
| 295914  | WELL                               | PR  | 10/18/2010        | OW  | 123-25854 | TURNER 21-34  | RI          |            |         |                               |             |        |      |    |            |    |           |              |    |
| <b>General Comment:</b><br><p style="color: blue;">This inspection is in response to Complaint #200440901. Corrective actions are shorter since this is a complaint.</p>  |                                    |   |                   |   |           |               |             |            |         |                               |             |        |      |    |            |    |           |              |    |

**Inspected Facilities**

Facility ID: 295914    Type: WELL    API Number: 123-25854    Status: PR    Insp. Status: RI

**Complaint**

Comment: This inspection is in response to Complaint #200440901 regarding reclamation efforts conducted by the Operator after a release on April 20, 2014, and concerns expressed by the complainant about the revegetation of the area. COGCC staff is requesting the Operator provide information while Complaint #200440901 is still under review. A follow up inspection will proceed after the Operator provides the requested information and further review is conducted.

Initial review found that approximately 460 cubic yards of soil was scraped to remove any residual surface contamination and approximately 10.0 acres seeded twice- Fall 2014 and Summer/Fall 2015- using the preferred landowner seed mix and crimped with straw. Based on a LT Environmental report submitted on May 22, 2014 titled "Documentation of Field Observations and Sample Results", a liquid bio-formulation (MicroBlaze) was applied to portions of the impacted area.

Corrective Action: Please provide the following information:

Date: 01/25/2017

- 1) Seed mix and seeding rate used during both applications in 2014 and 2015.
- 2) Specifics on the MicroBlaze microbes, nutrients and surfactants applied, and confirm the application rate used on the impacted area.
- 3) Application rate and mulch product used.
- 4) Provide any additional information if amendments were applied (i.e., nitrogen).

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 401188138    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4054290">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4054290</a> |