

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	NO WELL SIGN AT WELLHEAD		
Corrective Action:	Install sign to comply with Rule 210.a.	Date:	02/02/2017

Emergency Contact Number:

Comment:	OK, EMERGENCY NUMBER ON BATTERY SIGN	Date:	
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume			
Crude Oil	WELLHEAD	<= 1 bbl			
Comment:	SOILED DIRT AROUND WELLHEAD				
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.			Date:	02/02/2017
Crude Oil	Separator	<= 1 bbl			
Comment:	STAINED SOIL INSIDE SEP HOUSE FRON LEAKING 2" VALVE				
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.			Date:	02/02/2017

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	2" PIPE FENCE SE CORNER N40.00305 W-104.38654		
Corrective Action:		Date:	

Equipment:

Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		

Corrective Action:

Date:

Inspected FacilitiesFacility ID: 244914 Type: WELL API Number: 123-12709 Status: PR Insp. Status: SI**Idle Well**Purpose: Shut In Temporarily Abandoned Reminder: _____Comment: Corrective Action: Date: _____**COGCC Comments**

Comment	User	Date
INTERMITTER CONTROLLER ON WELLHEAD DOCUMENT # 685501095, DATED 10/26/16, STAINED SOIL NOT CLEANED UP AROUND WELLHEAD, STAINED SOIL INSIDE SEP HOUSE FROM 2" VALVE LEAKING	montoyaj	01/19/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401189351	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4055381
685501764	STAINED SOIL LEAKING 2" VALVE	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4055368
685501765	FITTING LEAKING BY 2" VALVE	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4055369
685501766	STAINED SOIL AT WELLHEAD	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4055370
685501767	STEM ON N=MASTER VALVE LEAKING ON GROUND	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4055371
685501768	NO WELL SIGN	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4055372