

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
01/19/2017
Submitted Date:
01/19/2017
Document Number:
685501770

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
323005 _____ MONTOYA, JOHN _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: K P KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Findings:

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
244626	WELL	PR	10/10/1985	GW	123-12421	Jordan #34-2	PR

General Comment:

(This area is intentionally left blank for general comments.)

Location			
Lease Road:			
Type	Main		
comment:			
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	OK		
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
Crude Oil	Separator	<= 1 bbl	
Comment:	2" VALVES LEAKING OIL ON EAST SIDE OF SEPERATOR, AND SEPERATOR NEEDS TO BE WASHED OUT OIL LEAKING ALL OVER INSIDE SEPERATOR		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: <u>02/02/2017</u>
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	2" PIPE FENCE		
Corrective Action:			Date:
Equipment:			
Type: Plunger Lift	#		corrective date
Comment:			
Corrective Action:			Date:
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 244626 Type: WELL API Number: 123-12421 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
INTERMITTER CONTROLLER ON WELLHEAD DOCUMENT # 685500996, DATED 10/13/16, NONE OF THE WORK HAS NOT BEEN COMPLETED FROM LAST INSPECTION	montoyaj	01/19/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401189355	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4055383
685501771	SOILED DIRT AT SEPERATOR	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4055373
685501772	2" VALVE LEAKING	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4055374
685501773	2" VALVE NEEDS REPAIRED LEAKING	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4055375
685501774	UNIT NEEDS CLEANED OUT	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4055376
685501775	UNIT NEEDS CLEANED OUT	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4055377