

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
01/25/2017
Submitted Date:
01/27/2017
Document Number:
675103295

FIELD INSPECTION FORM

Loc ID 314906 Inspector Name: GRANAHAN, KYLE On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
OGCC Operator Number: 16700
Name of Operator: CHEVRON USA INC
Address: 6301 DEAUVILLE BLVD
City: MIDLAND State: TX Zip: 79706

Findings:
2 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Peterson, Diane	970-675-3842	dlpe@chevron.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229868	WELL	IJ	06/01/2000	ERIW	103-07526	CARNEY C T 30 X 34	WK

General Comment:
Workover rig on location - performed cement bond log, conducted casing pressure test, run back in hole with new tools/tubing.

Inspected Facilities

Facility ID: 229868 Type: WELL API Number: 103-07526 Status: IJ Insp. Status: WK

Workover

Comment: Alliance workover rig #2 on location - performed cement bond log, conducted casing pressure test, run back in hole with new tools/tubing and await officail UIC MIT.

Corrective Action:

Date: