

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
01/26/2017
Submitted Date:
01/30/2017
Document Number:
682401737

FIELD INSPECTION FORM

Loc ID 448780 Inspector Name: Binschus, Chris On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10071
Name of Operator: BARRETT CORPORATION* BILL
Address: 1099 18TH ST STE 2300
City: DENVER State: CO Zip: 80202

Findings:

- 6 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
		COGCC_FIR@billbarrettcop.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
448781	WELL	DG	01/25/2017		123-44018	Will Trust 6-62-10-1719BN2	RI
448782	WELL	DG	01/24/2017		123-44019	Will Trust 6-62-10-1614B2	RI
448786	WELL	DG	01/26/2017		123-44023	Will Trust 6-62-10-1719BS2	RI
448787	WELL	DG	01/28/2017		123-44024	Will Trust 6-62-10-3335B2	RI
448788	WELL	DG	01/27/2017		123-44025	Will Trust 6-62-10-3230B2	RI

General Comment:

[This is a follow up stormwater inspection from the previous FIR Document #682401717 that was last inspected on January 20, 2017.](#)

Location Construction

Location ID: 448780 CDP: _____

Comment: _____

Corrective Action: _____ Date: _____

Form 2A COAs:

Comment: _____

Corrective Action: _____ Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____ Date: _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present
--------------	---------	------------	---------

WADDLES	Yes				
Comments: Erosion BMPs: Wattles have been installed along the outer perimeter of the sediment trap along the northeast location. Wattles have not been properly installed by trenching and backfilling the wattle, and wattles have not been overlapped at joints.					
Other BMPs: <input style="width:100%;" type="text"/>					
Corrective Action: Install BMP properly to ensure BMP properly functions.					Date: 02/06/2017

Comments: Erosion BMPs: Check dam BMP has been installed in conjunction with berm and ditch BMP. Appears more rock material could be added to capture sediment.					
Other BMPs: <input style="width:100%;" type="text"/>					
Corrective Action:					Date:

BERMS	Yes				
Comments: Erosion BMPs: Berm has not been built to a sufficient height and has not been compacted along the perimeter of location.					
Other BMPs: <input style="width:100%;" type="text"/>					
Corrective Action: Install a sufficient berm and compact berm to manage pollutant contributions to stormwater runoff from unconsolidated soil material. Typical recommended minimum height of a berm is 15 inches at a 3:1 slope.					Date: 02/06/2017

DITCHES	Yes				
Comments: Erosion BMPs: <input style="width:100%;" type="text"/>					
Other BMPs: <input style="width:100%;" type="text"/>					
Corrective Action:					Date:

Comment: BMPs should remain in place and in proper functioning condition until the location reaches final reclamation.

Corrective Action: **Date:** _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities

Facility ID: <u>448781</u>	Type: <u>WELL</u>	API Number: <u>123-44018</u>	Status: <u>DG</u>	Insp. Status: <u>RI</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

Facility ID: <u>448782</u>	Type: <u>WELL</u>	API Number: <u>123-44019</u>	Status: <u>DG</u>	Insp. Status: <u>RI</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

Facility ID: <u>448786</u>	Type: <u>WELL</u>	API Number: <u>123-44023</u>	Status: <u>DG</u>	Insp. Status: <u>RI</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

Facility ID: <u>448787</u>	Type: <u>WELL</u>	API Number: <u>123-44024</u>	Status: <u>DG</u>	Insp. Status: <u>RI</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

Facility ID: <u>448788</u>	Type: <u>WELL</u>	API Number: <u>123-44025</u>	Status: <u>DG</u>	Insp. Status: <u>RI</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

COGCC Comments

Comment	User	Date
Refer to attached inspection photos in Document #682401740.	binschusc	01/30/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682401740	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4063300