

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/27/2017

Submitted Date:

01/30/2017

Document Number:

678300644**FIELD INSPECTION FORM**
 Loc ID 318601 Inspector Name: GINTAUTAS, PETER On-Site Inspection ☐ 2A Doc Num:                     
**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**OGCC Operator Number: 46290Name of Operator: K P KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Findings:**1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Lara-Mesa, Susana	(303) 825-4822	cogcc@kpk.com	
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241702	WELL	PR	11/25/1986	OW	123-09491	ELKHORN COMPANY B 9	EI

**General Comment:**

tank battery not co-located with well and battery not inspected in this report  
 Follow-up inspection to 684902981 of 01/25/2017 for spill related issues only.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

cleanup of fresh spill noted in inspection 684902981 had been accomplished as shown in attached photos. Small excavation around well casing was also underway to remove any soils impacted by the active spill of 25Jan2017 and any soils below surface layer.  
Operator indicated production records and time of last pumper visit show spill was not of reportable volume  
Excavated soils stored on liner material to SE of wellhead

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 241702 Type: WELL API Number: 123-09491 Status: PR Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
678300645	spill response email	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4063581">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4063581</a>
678300646	wellhead exposed in excavation	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4063582">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4063582</a>
678300647	oil removed	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4063583">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4063583</a>