

Construction and Stormwater Inspection- Overview



Google Earth aerial photo taken 9/7/2013 of the Will Trust 6-62-10 11 location overview. An area of 5.25 acres was mapped on January 26, 2017 using a Trimble Juno 3B handheld device. Perimeter of the area mapped and highlighted in red.

Construction and Stormwater Inspection



Photo 1. Photo taken from the northwest location, facing East. Berm BMP insufficient and berm not compacted.

Construction and Stormwater Inspection



Photo 2. Photo taken from the northern location, facing East. Berm BMP insufficient along perimeter of location and berm not compacted.

Construction and Stormwater Inspection



Photo 3. Photo taken from the northern location, facing East. Berm BMP insufficient along perimeter of location and berm not compacted.

Construction and Stormwater Inspection



Photo 4. Photo taken from the eastern location, facing South. Berm BMP insufficient along perimeter of location and berm not compacted. BMP installed along the southeast location while COGCC staff was inspecting location.

Construction and Stormwater Inspection



Photo 5. Photo taken from the eastern location, facing South. Berm BMP insufficient along perimeter of location and berm not compacted. BMP installed along the southeast location while COGCC staff was inspecting location.

Construction and Stormwater Inspection



Photo 6. Photo taken from the eastern location, facing South. Berm BMP insufficient along perimeter of location and berm not compacted. BMP installed along the southeast location while COGCC staff was inspecting location.

Construction and Stormwater Inspection



Photo 7. Photo taken from the southeast location, facing Southwest. Berm BMP insufficient along perimeter of location and berm not compacted. BMP installed along the southeast location while COGCC staff was inspecting location.

Construction and Stormwater Inspection



Photo 8. Photo taken from the southern location, facing West. Berm BMP insufficient along perimeter of location and berm not compacted.

Construction and Stormwater Inspection



Photo 9. Photo taken from the southwest location, facing West. Berm BMP insufficient along perimeter of location and berm not compacted.