

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/20/2017

Submitted Date:

01/24/2017

Document Number:

680101461**FIELD INSPECTION FORM**

Loc ID 382731	Inspector Name: Colby, Lou	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 4 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested															
Operator Information: OGCC Operator Number: <u>47120</u> Name of Operator: <u>KERR MCGEE OIL & GAS ONSHORE LP</u> Address: <u>P O BOX 173779</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80217-</u>																			
Contact Information: <table border="1" style="width:100%"> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> <tr> <td></td> <td></td> <td>COGCCinspections@Anadarko.com</td> <td></td> </tr> </table>					Contact Name	Phone	Email	Comment			COGCCinspections@Anadarko.com								
Contact Name	Phone	Email	Comment																
		COGCCinspections@Anadarko.com																	
Inspected Facilities: <table border="1" style="width:100%"> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> <tr> <td>210290</td> <td>WELL</td> <td>PA</td> <td>06/01/1974</td> <td>DA</td> <td>045-06046</td> <td>NORTH RIFLE 3</td> <td>RI</td> </tr> </table>				Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	210290	WELL	PA	06/01/1974	DA	045-06046	NORTH RIFLE 3	RI
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status												
210290	WELL	PA	06/01/1974	DA	045-06046	NORTH RIFLE 3	RI												

General Comment:

This is a Final Reclamation Inspection for PA Well API#045-06046; Spud 11/20/1973 by Maguire Oil Co. Plugged and Abandoned 5/6/2005 by Westport Oil & Gas. Scout Card on this Well has it P&A in 1974. It received a Passing P&A Inspection 9/11/1991; later that year it was determined to be SI on heavily overgrown revegetated Location. Notes in 2006 Complaints Inspection say Fence was knocked down during Reclamation Work by Operator KERR-MCGEE OIL & GAS.

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: [Range Land](#)

Well plugged Pass Pit mouse/rat holes, cellars backfilled Pass

Debris removed Pass No disturbance /Location never built _____

Access Roads Regraded **Fail** Contoured **Fail** Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed **Fail** Locations, facilities, roads, recontoured **Fail**

Compaction alleviation _____ Dust and erosion control Pass

Non cropland: Revegetated 80% In Cropland: perennial forage _____

Weeds present **Fail** Subsidence Pass

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: [Access Road has not been Reclaimed, nor has site been re-contoured. It appears site has naturally revegetated; though Snow Cover prevented detailed Vegetation assessment. Items from previous Inspections have been resolved as there was no evidence of Pit or Debris. One area of Old growth Thistle \(B List Noxious Weed\) was noted as well as remnants of Annual Weed Growth. To reiterate; Well was plugged in 2005 not 1974 as stated on Scout Card.](#)

Inspector Name: Colby, Lou

Corrective Action:	Perform Final Reclamation per COGCC 1004 Rules; Reclamation Activities to be complete by June 15, 2017.			Date	06/15/2017	
Overall Final Reclamation	Fail	Well Release on Active Location	<input type="checkbox"/>	Multi-Well Location	<input type="checkbox"/>	
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment:				Location appeared Stable though Snow Cover prevented detailed SW Inspection.		
Corrective Action:				Date:		
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401193204	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4058986
680101462	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4058984