

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
01/13/2017
Submitted Date:
01/31/2017
Document Number:
680301620

FIELD INSPECTION FORM

Loc ID 313954 Inspector Name: SCHURE, KYM On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 53790
Name of Operator: MARKUS PRODUCTION, INC
Address: 39 FAIRWAY LANE
City: LITTLETON State: CO Zip: 80123

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|---------------------------|---------|
| Brown, Mark | | mark@markusproduction.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------------|-------------|
| 89322 | WELL | PR | 04/03/2000 | OW | 087-08106 | NB WICKSTROM-STATE 42-16 | PA |

General Comment:

[P&A Inspection Day \(3\) Form 6 Doc# 401047481](#)

Location

| | | | |
|--------------------|------------------------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Satisfactory Two track | | |
| Corrective Action: | | Date: | |

Overall Good:

| | | | |
|----------------------|--------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Satisfactory | | |
| Corrective Action: | | Date: | |

| | | | |
|----------------------------------|--------------|-------|--|
| Emergency Contact Number: | | | |
| Comment: | Satisfactory | | |
| Corrective Action: | | Date: | |

Overall Good:

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

Multiple Spills and Releases?

| | | | |
|--------------------|----------------|-------|--|
| Fencing/: | | | |
| Type | LOCATION | | |
| Comment: | Livestock wire | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|---|-------|-----------------|
| Equipment: | | | |
| Type: Other | # 0 | | corrective date |
| Comment: | Equipment remains on-site. Upon completion of P&A remove all equipment and begin surface reclamation process. | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Venting: | | | |
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 89322 Type: WELL API Number: 087-08106 Status: PR Insp. Status: PA

Cement

Cement Contractor

Contractor Name: Yetter Well Service

Contractor Phone: 970-522-2885

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): 6435,1400

Cement Volume (sx): 40+40

Good Return During Job: _____

Cement Type: #15

Comment: Rig up for tubing, hydro-test tubing @ 6000psi., found (3) holes/split, replace damaged tubing, trip with stinger, sting into retainer, pump (40) sks 15G cement. Perf. @ 1400', set retainer, sting in, pump (40) sks #15 cement, cap off and shut in well.

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Other | In Process | Other | In Process | | | |

Comment: [Use BMP's for stormwater erosion management until final reclamation approval is attained from COGCC.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT