




Photo#1: View of Location from Entry to NE.

January 30, 2017

Inspection Photos: Ursa Weinreis ALS

Photo#2:

AL Well with Conductor Set ; Operator has met Safety Standards for Maintaining a Preset Conductor.





Photo#4: View of Well Corral to SE.

Inspection Photos: Ursa Weinreis ALS

January 30, 2017

Photo#5:

AL Well with Conductor Set ; Operator has met Safety Standards for Maintaining a Preset Conductor

Photo#6:

