

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/01/2017

Submitted Date:

02/01/2017

Document Number:

667600097**FIELD INSPECTION FORM**
 Loc ID 320283 Inspector Name: Kraich, Adam On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10548Name of Operator: HRM RESOURCES II LLCAddress: 410 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**18 Number of Comments6 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Smith, Brandy	303-339-8600	bsmith@hrmresoures.net	<a href="tel:303-893-6621">303-893-6621</a>
Prohaska, April	(303) 996-8697	aprohaska@hrmres.com	
Pape, Terry	970-768-5700	tpape@hrmres.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203350	WELL	PR	03/31/2008	GW	001-08859	AMOCO 44-17	PR

**General Comment:**

### Location

<b>Lease Road:</b>			
Type	Access		
comment:	Two track through farm ground.		
Corrective Action		Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Sign at wellhead identifies well as Amoco #24-17. Well is actually #44-17. The sign at the #24-17 identifies as the #44-17. Sign need swapped.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	03/01/2017

Emergency Contact Number:

Comment:	Adequate.	
Corrective Action:		Date: _____

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Uncontrolled weeds and vegetation within 25' of wellhead. See attached photos.		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	03/01/2017
Type	DEBRIS		
Comment:	Weeds and debris on south edge of tank battery, piles of rubble on north edge of lease road at well head, and roll of wire fencing on west side of battery. See attached photos.		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	03/01/2017
Type	UNUSED EQUIPMENT		
Comment:	Farm equipment stored next to well head. See attached photos.		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	05/01/2017

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		

Comment:	Four wire barbed wire around battery.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Rod fence around wellhead.		
Corrective Action:		Date:	

**Equipment:**

Type: Emission Control Device	# 1		corrective date
Comment:	Pilot light not light.		
Corrective Action:	Light pilot light.	Date:	02/03/2017
Type: Bird Protectors	# 2		
Comment:	Avian protection measures installed on separator exhaust and ECD.		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 2		
Comment:	Two anchors at battery fence.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	STEEL AST		,	
Comment:	70 BBL					
Corrective Action:					Date:	

**Paint**

Condition	Inadequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance			
Earth	Adequate		Walls Sufficent		Base Sufficient		Adequate			
Comment:										
Corrective Action:								Date:		
Contents		#	Capacity	Type		Tank ID	SE GPS			

CONDENSATE	1	300 BBLs	STEEL AST		
Comment: Tank is not painted adequately. See attached photo.					
Corrective Action: Paint tanks per Rule 804.					Date: 07/01/2017
<b>Paint</b>					
Condition	Inadequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
<b>Venting:</b>					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:					Date:

**Inspected Facilities**Facility ID: 203350 Type: WELL API Number: 001-08859 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
667600118	Amoco 44-17 Inspection	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4065542">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4065542</a>