

Complaint and Stormwater Inspection

02/03/2017

Operator: Kerr McGee #47120

Location ID: 444427

Weld County, CO

SEESW Section 23 T1N R67W

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO

Department of Natural Resources



Figure 1: Photo taken from the northeast corner of the location, facing west. Photo shows ditch along the perimeter of the location constructed as a stormwater and sediment control BMP.



Figure 2: Photo taken from the northeast corner of the location, facing south. Photo shows ditch along the perimeter of the location constructed as a stormwater and sediment control BMP. Pump jack and well seen in photo not associated with the location in this inspection.



Figure 3: Photo taken east of the location, facing south. Photo shows hay field on the adjacent surface owners property, the location, and a Pump jack and well not associated with location in this inspection.



Figure 4: Photo taken from the northeast end of the location, facing south. Photo shows soil and disturbances from the location had encroached onto the adjacent surface owners hay field.



Figure 5: Photo taken from the east end of the location, facing south. Photo shows stakes used to define the property lines. Note disturbances had encroached upon the adjacent surface owners property.



Figure 6: Photo taken from the east end of the location, facing south. Photo shows a five (5) foot wide strip on the adjacent surface owner's land that is void of vegetation due to disturbances caused during construction.



Figure 7: Photo taken from the east end of the location. Photo shows an additional 3 foot wide strip (right of red line) of grass further into the complainant's property that appears to have been impacted from the disturbance.



Figure 8: Photo taken from inspection doc. #682401425. This was a construction, pre-drill inspection. Photo shows ditch on the east end of the location, and the soil deposited on the adjacent surface owners property. Stakes shown with yellow arrow marks property line.



Figure 9: Photo taken from inspection doc. #682401425. This was a construction, pre-drill inspection. Photo shows ditch on the east end of the location, and the soil deposited on the adjacent surface owners property. Stakes shown with yellow arrow marks property line.



Figure 10: Photo taken from the southeast end of the location, facing north. Photo shows soil and disturbances from the location had encroached onto the adjacent surface owners hay field.



Figure 11: Photo taken from the southeast corner of the location, facing west. Photo shows ditch along the perimeter of the location constructed as a stormwater and sediment control BMP.



02.03.2017 09:55

Figure 12: Photo taken from the southwest corner of the location, facing east. Photo shows ditch along the perimeter of the location constructed as a stormwater and sediment control BMP



Figure 13: Photo taken from the southwest corner of the location, facing north. Photo shows ditch along the perimeter of the location constructed as a stormwater and sediment control BMP. Photo also shows topsoil stockpile.



Figure 14: Photo taken from the northwest end of the location, near location entrance. Photo shows one of two sediment traps used as a stormwater and sediment control BMP.



Figure 15: Photo taken from the northwest end of the location, near location entrance. Photo shows one of two sediment traps used as a stormwater and sediment control BMP.



Figure 16: Photo taken from the northwest end of the location. Photo shows second sediment trap use as a stormwater and sediment control BMP.



Figure 17: Photo taken from the northwest corner of the location, facing south. Photo shows ditch along the perimeter of the location constructed as a stormwater and sediment control BMP.



Figure 18: Photo taken from the northwest corner of the location, facing east. Photo shows ditch along the perimeter of the location, and sediment trap constructed as a stormwater and sediment control BMPs.