

Interim Reclamation and Stormwater Inspection

01/26/2017

Operator: Bonanza Creek

Location ID: 428002

Weld County, CO

NENW Section 34 T7N R62W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Interim Reclamation and Stormwater Inspection



Photo 1. Photo taken from the northeast interim area, facing Northeast. Cut slope lacks vegetative growth for stabilization but did not observe any erosion occurring.

Interim Reclamation and Stormwater Inspection



Photo 2. Photo taken from the northern location, facing West. Cut slope lacks vegetative growth for stabilization but did not observe any erosion occurring.

Interim Reclamation and Stormwater Inspection



Photo 3. Photo taken from the northwest interim area, facing South. Germination apparent throughout most of the interim area.

Interim Reclamation and Stormwater Inspection



Photo 4. Photo taken from the western interim area, facing South. Germination apparent throughout most of the interim area. Perennial vegetative growth established along entire perimeter of location to help stabilize location from erosion.

Interim Reclamation and Stormwater Inspection



Photo 5. Photo taken from the southwest interim area, facing Southeast. Germination apparent throughout most of the interim area.

Interim Reclamation and Stormwater Inspection



Photo 6. Photo taken from the southern interim area, facing East. Germination lacks along portion of this interim area. May need additional reclamation activities to be performed to achieve Rule 1003 standards.

Interim Reclamation and Stormwater Inspection



Photo 7. Photo taken from the southeast location, facing East. Perennial vegetative growth established along entire perimeter of location to help stabilize location from erosion.

Interim Reclamation and Stormwater Inspection



Photo 8. Photo taken from the eastern interim area, facing North. Germination apparent throughout most of the interim area. Perennial vegetative growth established along entire perimeter of location to help stabilize location from erosion.

Interim Reclamation and Stormwater Inspection



Photo 9. Photo taken from the northern interim area, facing West. Germination lacks along portion of this interim area. May need additional reclamation activities to be performed to achieve Rule 1003 standards.