

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/26/2017

Submitted Date:

01/30/2017

Document Number:

682401734**FIELD INSPECTION FORM**
 Loc ID 436885 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 10071Name of Operator: BARRETT CORPORATION\* BILLAddress: 1099 18TH ST STE 2300City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCC_FIR@billbarrettcorp.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
436884	WELL	DG	12/16/2016	LO	123-39313	Ruh 6-62-11-0857B2	RI
436886	WELL	DG	12/15/2016	LO	123-39314	Ruh 6-62-11-0659B2	RI
436887	WELL	DG	12/14/2016	LO	123-39315	RUH 6-62-11-0560B2	RI
436888	WELL	DG	12/16/2016	LO	123-39316	Ruh 6-62-11-0758B2	RI

**General Comment:**

This is a follow up stormwater inspection from the previous FIR Document #682401719 that was last inspected on January 20, 2017.

**Location Construction**Location ID: 436885 CDP: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Form 2A COAs:**

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Wildlife BMPs:**

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Stormwater:**

Erosion BMPs	Present	Other BMPs	Present
--------------	---------	------------	---------

DITCHES	Yes		
Comments: Erosion BMPs: <span style="color: red;">Ditch has been installed in conjunction with berm. Ditch should be installed at a 2:1 or flatter slope on both sides.</span>			
Other BMPs: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>			
Corrective Action:		Date:	
BERMS	Yes		
Comments: Erosion BMPs: <span style="color: red;">Berm has been built to a sufficient height but has not been consistently compacted along the perimeter of location.</span>			
Other BMPs: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>			
Corrective Action: <span style="color: red;">Compact berm to manage pollutant contributions to stormwater runoff from unconsolidated soil material.</span>		Date: 02/06/2017	
WADDLES	Yes		
Comments: Erosion BMPs: <span style="color: red;">Wattles have been installed along the southern perimeter of location. Equipment traffic has damaged the wattles along portions of the installation. Wattles have not been properly installed by trenching and backfilling the wattle.</span>			
Other BMPs: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>			
Corrective Action: <span style="color: red;">Replace or repair where equipment has damaged BMP and install BMP properly to ensure BMP properly functions.</span>		Date: 02/06/2017	
Comments: Erosion BMPs: <span style="color: red;">Check dam BMP has been installed in conjunction with berm and ditch BMP.</span>			
Other BMPs: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>			
Corrective Action:		Date:	

**Comment:** BMPs should remain in place and in proper functioning condition until the location reaches final reclamation.

**Corrective Action:****Date:** \_\_\_\_\_

### **On Site Inspection (305):**

#### Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_  
 Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

#### Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_  
 Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

#### LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

#### Summary of Landowner Issues:

#### Summary of Operator Response to Landowner Issues:

#### Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

**Inspected Facilities**

Facility ID: <u>436884</u>	Type: <u>WELL</u>	API Number: <u>123-39313</u>	Status: <u>DG</u>	Insp. Status: <u>RI</u>
Facility ID: <u>436886</u>	Type: <u>WELL</u>	API Number: <u>123-39314</u>	Status: <u>DG</u>	Insp. Status: <u>RI</u>
Facility ID: <u>436887</u>	Type: <u>WELL</u>	API Number: <u>123-39315</u>	Status: <u>DG</u>	Insp. Status: <u>RI</u>
Facility ID: <u>436888</u>	Type: <u>WELL</u>	API Number: <u>123-39316</u>	Status: <u>DG</u>	Insp. Status: <u>RI</u>

**COGCC Comments**

Comment	User	Date
<a href="#">Refer to attached inspection photos in Document #682401736.</a>	binschusc	01/30/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401197161	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4062917">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4062917</a>
682401736	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4062916">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4062916</a>