

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
01/13/2017  
Submitted Date:  
01/31/2017  
Document Number:  
680301577

**FIELD INSPECTION FORM**

Loc ID 313954 Inspector Name: SCHURE, KYM On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 53790  
Name of Operator: MARKUS PRODUCTION, INC  
Address: 39 FAIRWAY LANE  
City: LITTLETON State: CO Zip: 80123

**Findings:**

9 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Brown, Mark		mark@markusproduction.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
89322	WELL	PR	04/03/2000	OW	087-08106	NB WICKSTROM-STATE 42-16	PA

**General Comment:**

P&A Inspection Day (4) Final Satisfactory Service contractor has agreed to notify Inspector Schure a.s.a.p. when well head is cut off (4') blow grade, cap w/info. welded on and ready for backfill.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Satisfactory Two track		
Corrective Action:			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Satisfactory		
Corrective Action:			Date:

<b>Emergency Contact Number:</b>			
Comment:	Satisfactory		
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Livestock wire		
Corrective Action:			Date:

<b>Equipment:</b>			
Type: Other	# 0		corrective date
Comment:	Surface equipment remains on-site. Upon completion of P&A remove all equipment and begin surface reclamation process.		
Corrective Action:			Date:

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:			Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 89322 Type: WELL API Number: 087-08106 Status: PR Insp. Status: PA

**Cement**

Cement Contractor

Contractor Name: Yetter Well Service

Contractor Phone: 970-522-2885

Surface Casing

Cement Volume (sx): 50+15

Circulate to Surface: YES

Cement Fall Back: \_\_\_\_\_

Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): 40+100+40

Good Return During Job: YES

Plugging Operations

Depth Plugs(feet range): 6435,5700,1400,355

Cement Volume (sx): 40+100+40+50+1

Good Return During Job: YES

Cement Type: #15 +15 G

Comment: Day (4) Rig wireline perf. @ 355, pump (50)sk on cement down casing, pump (15) sks cement for surface plug. P&A Complete  
 SATISFACTORY - Surface equipment remains on-site. Remove all equipment and begin surface reclamation process.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	In Process	Other	In Process			

Comment: [Use BMP's for stormwater erosion management until final reclamation has been approved by COGCC.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<a href="#">P&amp;A Complete</a> SATISFACTORY	schureky	01/31/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401198853	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4064606">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4064606</a>