

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
02/02/2017  
Submitted Date:  
02/02/2017  
Document Number:  
685501898

**FIELD INSPECTION FORM**

Loc ID 319737 Inspector Name: MONTOYA, JOHN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 31257  
Name of Operator: FRITZLER RESOURCES INC  
Address: P O BOX 114  
City: FORT MORGAN State: CO Zip: 80701

**Findings:**

- 8 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Fritzler, Gene	970-768-0845	gfritzler@bresnan.net	<a href="#">left msg 9/21</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201199	WELL	PR	09/18/2014	OW	001-06602	LINNEBUR 1	SI

**General Comment:**

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	<input type="text" value="OK"/>		
Corrective Action:	<input type="text"/>		Date: _____
<b>Good Housekeeping:</b>			
Type	TRASH		
Comment:	TRASH INSIDE TREATER HOUSE AND BY EAST PROD TANK		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.		Date: <u>03/09/2017</u>
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
Crude Oil	Treater	<= 1 bbl	
Comment:	SOILED DIRT INSIDE TREATER HOUSE		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: <u>03/09/2017</u>
Crude Oil	Tank	<= 1 bbl	
Comment:	SOILED DIRT ON SOUTH SIDE OF TANKS		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: <u>03/09/2017</u>
In Containment: Yes _____			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Vertical Heater Treater	#		corrective date
Comment:			
Corrective Action:		Date:	

<b>Tanks and Berms:</b>					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	CONCRETE SUMP/VAULT		39.582610,-103.561630
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment: NO BERM AROUND CONCRETE VAULT				
Corrective Action: Location is within an exception zone, repair or install berms or other secondary containment devices per Rule 604.c.(3)B.				Date: 03/09/2017

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		39.582580,-104.561150
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Sufficient	Base Insufficient	Inadequate
Comment: BERMS WILL NOT HOLD CAPACITY OF PROD TANK				
Corrective Action: Location is within an exception zone, repair or install berms or other secondary containment devices per Rule 604.c.(3)B.				Date: 04/06/2017

**Venting:**

Yes/No	NO
Comment:	
Corrective Action:	
Date:	

**Flaring:**

Type	
Comment:	
Corrective Action:	
Date:	

**Inspected Facilities**Facility ID: 201199 Type: WELL API Number: 001-06602 Status: PR Insp. Status: SI**Idle Well**Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Corrective Action:  Date: \_\_\_\_\_**COGCC Comments**

Comment	User	Date
CAN'T GET INTO WELLHEADS NO KEYS FOR GATES, BOTH WELLS HAVE PUMP JACKS	montoyaj	02/02/2017

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401201034	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4066474">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4066474</a>
685501899	SOILED DIRT AND TRASH I NSIDE TREATER HOUSE	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4066438">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4066438</a>
685501900	SOILED DIRT INSIDE TREATER HOUSE	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4066440">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4066440</a>
685501901	BATTERY SIGN	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4066441">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4066441</a>
685501902	BERMS NEED REPAIRED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4066442">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4066442</a>
685501903	SOILED DIRT BEHIND TANKS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4066443">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4066443</a>
685501904	NO SIGNAGE ON WATER TANK	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4066445">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4066445</a>
685501905	HOLES IN TREATER RTEPLACE TREATER	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4066446">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4066446</a>
685501906	SOILED DIRT INSIDE AND TRASH	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4066447">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4066447</a>