

Photo#1:

View from East end of Well Row to West ; showing that Risers/Associated Facilities have been removed



Photo#2:



Photo#3:

View from West end of Well Line to East showing that Risers/Associated Facilities have been removed.



Photo#5:

Close up of area where Risers/Associated Facilities have been removed.



February 2, 2017

Inspection Photos: Encana PAs Schaeffer API#045-07398 -045-07388