

**Inspection Photos**  
**Location Name: Rollie J Vincent A 1**  
**API: 05-123-12556**



**Prior inspection photo for comparison purposes only**



**Photo 1: Stained soil at wellhead.**



**Inspection Photos**  
**Location Name: Rollie J Vincent A 1**  
**API: 05-123-12556**



**Prior inspection photo for comparison purposes only**



**Photo 2: Weeds controlled at tank battery, looking S**



**Inspection Photos**  
**Location Name: Rollie J Vincent A 1**  
**API: 05-123-12556**



**Prior inspection photo for comparison purposes only**



**Photo 3: Stained soil at loadout, E tank**



**Inspection Photos**  
**Location Name: Rollie J Vincent A 1**  
**API: 05-123-12556**



**Prior inspection photo for comparison purposes only**



**Photo 4: Stained soil at loadout, W tank**



**Inspection Photos**  
**Location Name: Rollie J Vincent A 1**  
**API: 05-123-12556**



**Prior inspection photo for comparison purposes only**



**Photo 5: Weeds controlled at tank battery, looking S**

**Inspection Photos**  
**Location Name: Rollie J Vincent A 1**  
**API: 05-123-12556**



**Prior inspection photo for comparison purposes only**



**Photo 6: Weeds controlled at separator**



**Inspection Photos**  
**Location Name: Rollie J Vincent A 1**  
**API: 05-123-12556**



**Prior inspection photo for comparison purposes only**



**Photo 7: Stained soil in separator house**



**Inspection Photos**  
**Location Name: Rollie J Vincent A 1**  
**API: 05-123-12556**



**Photo 8: Unused angle iron fencing**



**Photo 9: Tank battery fence in disrepair**