

Inspection Photos
Location Name: Elkhorn Company B-6
API: 05-123-09488



Photo from prior inspection for comparison purposes



Photo 1: Stained soil removed at wellhead



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Elkhorn Company B-6
API: 05-123-09488



Photo from prior inspection for comparison purposes



Photo 2: Stained soil around tank



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Elkhorn Company B-6
API: 05-123-09488



Photo from prior inspection for comparison purposes



Photo 3: Stained soil at hatch



Inspection Photos
Location Name: Elkhorn Company B-6
API: 05-123-09488



Photo from prior inspection for comparison purposes



Photo 4: stained soil between tanks



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Elkhorn Company B-6
API: 05-123-09488



Photo from prior inspection for comparison purposes



Photo 5: Stained soil at produced water tank



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Elkhorn Company B-6
API: 05-123-09488



Photo from prior inspection for comparison purposes



Photo 6: Stained soil at produced water tank



Inspection Photos
Location Name: Elkhorn Company B-6
API: 05-123-09488



Photo from prior inspection for comparison purposes



Photo 7: Stained soil at NW corner of separator



Inspection Photos
Location Name: Elkhorn Company B-6
API: 05-123-09488



Photo from prior inspection for comparison purposes



Photo 8: Stained soil in separator house



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Elkhorn Company B-6
API: 05-123-09488



Photo 9: Stained soil at manifold

