

**FORM
INSP**Rev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/13/2017

Submitted Date:

02/13/2017

Document Number:

674103933**FIELD INSPECTION FORM**

Loc ID 440920 Inspector Name: Rickard, Jeff On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
General, All inspections	(970) 332-3520	cogccinspection@pdce.com	All PDC inspection
Adamczyk, Megan		megan.adamczyk@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
440898	WELL	DG	05/04/2016	LO	123-41168	Jacobucci 32K-323	WK
440899	WELL	DG	04/18/2016	LO	123-41169	Jacobucci 32K-403	WK
440901	WELL	DG	04/11/2016	LO	123-41170	Jacobucci 32K-243	WK
441060	WELL	DG	03/31/2016	LO	123-41250	Jacobucci 32K-443	WK

General Comment:

Inspected Facilities

Facility ID: 440898 Type: WELL API Number: 123-41168 Status: DG Insp. Status: WK

Complaint

Comment: [Complaint #:200441037](#)

Field Inspector Assigned: Jeff Rickard

Location #: 440920

Inspection Document #: 674103933

Nature of complaint: Noise

If Sound GPS Coordinates of Survey Location:NA

Inspection Observations:

OGCC inspector was on location on 2/13/17, winds were still too high to run a sound survey being 13 mph out of the north. The original location that the complaint was filed under is no longer being frac'd, instead the frac fleet is on the location immediately adjacent to the east. PDC has put up additional bales on the south side of the new location for sound mitigation.

Corrective Action:

Date:

BradenHead

Comment: [Braden head is exposed at surface.](#)

Corrective Action:

Date:

Completion

Operation:

Date Flowback:

Contractor:

Comment: [Frac complete, awating flowback.](#)

Corrective Action:

Date:

Facility ID: 440899 Type: WELL API Number: 123-41169 Status: DG Insp. Status: WK

BradenHead

Comment: [Braden head is exposed at surface.](#)

Corrective Action:

Date:

Completion

Operation:

Date Flowback:

Contractor:

Comment: [Frac complete, awating flowback.](#)

Corrective Action:

Date:

Facility ID: 440901 Type: WELL API Number: 123-41170 Status: DG Insp. Status: WK

BradenHead

Comment: Braden head is exposed at surface.

Corrective Action:

Date: _____

Completion

Operation:

Date Flowback:

Contractor:

Comment: Frac complete, awating flowback.

Corrective Action:

Date: _____

Facility ID: 441060 Type: WELL API Number: 123-41250 Status: DG Insp. Status: WK

BradenHead

Comment: Braden head is exposed at surface.

Corrective Action:

Date: _____

Completion

Operation:

Date Flowback:

Contractor:

Comment: Frac complete, awating flowback.

Corrective Action:

Date: _____

COGCC Comments

Comment	User	Date
Complaint #:200441037	rickardj	02/13/2017
Field Inspector Assigned: Jeff Rickard		
Location #: 440920		
Inspection Document #: 674103933		
Nature of complaint: Noise		
If Sound GPS Coordinates of Survey Location:NA		
Inspection Observations:		
OGCC inspector was on location on 2/13/17, winds were still too high to run a sound survey being 13 mph out of the north. The original location that the complaint was filed under is no longer being frac'd, instead the frac fleet is on the location immediately adajacent to the east. PDC has put up additional bales on the south side of the new location for sound mitigation.		