

**FORM
INSP**Rev
X/15

State of Colorado Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

01/17/2017

Submitted Date:

02/03/2017

Document Number:

672500325**FIELD INSPECTION FORM**
 Loc ID 305447 Inspector Name: Gomez, Jason On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 370 17TH STREET #2170City: DENVER State: CO Zip: 80202**Status Summary:**☒ THIS IS A FOLLOW UP INSPECTION☐ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		Cogcc.inspections@crestone pr.com	
Adamczyk, Megan		megan.adamczyk@state.co.u s	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434334	WELL	DG	11/03/2016	LO	123-38105	Woolley Becky 2F-7H-E168	DG
434336	WELL	DG	11/01/2016	LO	123-38107	Woolley Becky 2D-7H-E168	DG
434338	WELL	DG	10/30/2016	LO	123-38109	Woolley Becky 2B-7H-E168	DG
434340	WELL	DG	10/29/2016	LO	123-38111	Woolley Becky 2A-7H-E168	DG
434341	WELL	DG	11/02/2016	LO	123-38112	Woolley Becky 2E-7H-E168	DG
436731	WELL	DG	10/31/2016	LO	123-39241	Woolley Becky 2C-7H-E168	DG

General Comment:

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type	Field Flare	
Comment:	NOT IN USE AT TIME OF INSPECTION	
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 434334 Type: WELL API Number: 123-38105 Status: DG Insp. Status: DG**Complaint**Comment: COMPLAINT# 200440949 and 200440980.

Corrective Action:

Date:

Facility ID: 434336 Type: WELL API Number: 123-38107 Status: DG Insp. Status: DGFacility ID: 434338 Type: WELL API Number: 123-38109 Status: DG Insp. Status: DGFacility ID: 434340 Type: WELL API Number: 123-38111 Status: DG Insp. Status: DGFacility ID: 434341 Type: WELL API Number: 123-38112 Status: DG Insp. Status: DGFacility ID: 436731 Type: WELL API Number: 123-39241 Status: DG Insp. Status: DG

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass			Covering Materials	Pass	
Rip Rap	Pass					
Compaction	Pass			Vehicle Tracking	Pass	
Gravel	Pass			Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
THIS INSPECTION WAS FOLLOW UP TO COMPLAINT# 200440949. ALL RIG LIGHTING WAS POINTED DOWN AND TOWARD THE GROUND. ACCORDING TO RIG MANAGER REGULAR DRILLING OPERATIONS WERE RECORDED DURING THE TIME OF THE COMPLAINTS COMPLAINT. NO VIOLATIONS OF COGCC RULES WERE OBSERVED AT THE TIME OF INSPECTION.	gomezj	02/03/2017