

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/09/2017

Submitted Date:

02/15/2017

Document Number:

673404075**FIELD INSPECTION FORM**
 Loc ID 314513 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 16700Name of Operator: CHEVRON USA INCAddress: 6301 DEAUVILLE BLVDCity: MIDLAND State: TX Zip: 79706**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name     | Phone | Email            | Comment            |
|------------------|-------|------------------|--------------------|
| Archuleta, Chris |       | cfvy@chevron.com | Wilson Creek Field |
| Dixon, Fairl     |       | fdix@chevron.com | Wilson Creek field |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name        | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------|-------------|
| 228887      | WELL | PR     | 07/17/1991  | OW         | 103-05882 | WILSON CREEK UNIT 15 | PR          |

**General Comment:**

**Location**Overall Good: ☒**Signs/Marker:**

|                    |            |       |  |
|--------------------|------------|-------|--|
| Type               | CONTAINERS |       |  |
| Comment:           |            |       |  |
| Corrective Action: |            | Date: |  |
| Type               | WELLHEAD   |       |  |
| Comment:           |            |       |  |
| Corrective Action: |            | Date: |  |

Emergency Contact Number:

Comment: 970-824-6452

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

|                          |     |       |                 |
|--------------------------|-----|-------|-----------------|
| Type: Deadman # & Marked | # 4 |       | corrective date |
| Comment:                 |     |       |                 |
| Corrective Action:       |     | Date: |                 |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

|                             |                      |                       |            |                  |
|-----------------------------|----------------------|-----------------------|------------|------------------|
| <b>Inspected Facilities</b> |                      |                       |            |                  |
| Facility ID: 228887         | Type: WELL           | API Number: 103-05882 | Status: PR | Insp. Status: PR |
| <b>Producing Well</b>       |                      |                       |            |                  |
| Comment:                    | Central tank battery |                       |            |                  |
| Corrective Action:          |                      |                       |            | Date:            |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: No apparent soil migration; erosion or soil movement.

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT