

# Reclamation Inspection

02/13/2017

Operator: Davis, LLC\* Edwards Mike #22755

Location ID: 419744

Washington County, CO

SWNE Section 34 T2S R49W

Inspection Doc. Number: 682501649

Aaron Trujillo

Reclamation Specialist

COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator: Davis, LLC\* Edwards Mike #22755  
Location ID: 419744



**Figure 1:** Photo taken from location. Photo shows starting point for the disturbance area transect, facing northwest. Photo shows vegetation over the reclamation area.

Inspection Photos  
Operator: Davis, LLC\* Edwards Mike #22755  
Location ID: 419744



**Figure 2:** Photo taken from the 50<sup>th</sup> point of the disturbance area transect, facing southwest.



**Figure 3:** Photo taken from the 50<sup>th</sup> point of the disturbance area transect, facing southwest.



Inspection Photos  
Operator: Davis, LLC\* Edwards Mike #22755  
Location ID: 419744



**Figure 4:** Photo taken from the 50<sup>th</sup> point of the disturbance transect. Photo shows vegetative cover at the 50<sup>th</sup> point.



Inspection Photos  
Operator: Davis, LLC\* Edwards Mike #22755  
Location ID: 419744



**Figure 5:** Photo taken from the end point of the disturbance transect, facing southeast. Photo shows vegetative cover at the 50<sup>th</sup> point. Photo shows vegetation over the reclamation area.

Inspection Photos  
Operator: Davis, LLC\* Edwards Mike #22755  
Location ID: 419744



**Figure 6:** Photo of the starting point of the reference transect, facing south. Photo shows vegetation over the reference area.



Inspection Photos  
Operator: Davis, LLC\* Edwards Mike #22755  
Location ID: 419744



**Figure 7:** Photo taken from the 50<sup>th</sup> point of the reference area transect, facing east.



**Figure 8** Photo taken from the 50<sup>th</sup> point of the reference area transect, facing west.



Inspection Photos  
Operator: Davis, LLC\* Edwards Mike #22755  
Location ID: 419744



**Figure 9:** Photo taken from the 50<sup>th</sup> point of the reference transect. Photo shows vegetative cover at the 50<sup>th</sup> point.



Inspection Photos  
Operator: Davis, LLC\* Edwards Mike #22755  
Location ID: 419744



**Figure 10:** Photo taken from the end point of the reference transect, facing north. Photo shows vegetative cover at the 50<sup>th</sup> point. Photo shows vegetation over the reclamation area.