

Inspection Photos
Location Name: Andrews 16-7
API: 05-123-14881



Photo from prior inspection for comparison purposes



Photo 1: Stained soil at wellhead



Inspection Photos
Location Name: Andrews 16-7
API: 05-123-14881



Photo from prior inspection for comparison purposes



Photo 2: Sign put in at wellhead. Stained soil where pump jack used to be. Looking W.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources