

Inspection Photos
Location Name: Peters 1
API: 05-123-07170



Photo from prior inspection for comparison purposes



Photo 1: No contents, capacity on fiberglass tank



Inspection Photos
Location Name: Peters 1
API: 05-123-07170



Photo from prior inspection for comparison purposes



Photo 2: Stained soil from prior CA has been addressed.



Inspection Photos
Location Name: Peters 1
API: 05-123-07170



Photo from prior inspection for comparison purposes



Photo 3: Operator signage has been updated per CA.



Inspection Photos
Location Name: Peters 1
API: 05-123-07170



Photo 4: Low berms at loadout valve