

Inspected Facilities

Facility ID: 247800 Type: WELL API Number: 123-15598 Status: PR Insp. Status: TA

Complaint

Comment:

Complaint #:200441074
 Field Inspector Assigned: Jeff Rickard
 Well Number: 05-123-15598
 Inspection Document #:674103930
 Nature of complaint: Noise, Odor, Dust
 If Sound GPS Coordinates of Survey Location:NA
 Inspection Observations:
 An inspection of the above location was conducted with focus on noise, odor and dust. It was observed that Anadarko is upgrading/replacing the battery at the location. The old equipment is being hauled out and new equipment is being hauled in. The new equipment includes Tanks, Separators, and ECD's. OGCC inspector did observe dust coming from lease road when trucks drove on it, but did not observe any rule violations related to maintenance or storm water of the access road or location. The nearest NOAA weather station recorded wind gusts of 71mph today and winds still continue to be high which accounts for the dust being kicked up. No odors were observed by OGCC staff at time of inspection.
 18A DOC#200441076

Corrective Action:

Date:

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: TA

Corrective Action: _____

Date: _____

BradenHead

Comment: Braden head is exposed at surface.

Corrective Action: _____

Date: _____

COGCC Comments

| Comment | User | Date |
|--|----------|------------|
| <p>Complaint #:200441074</p> <p>Field Inspector Assigned: Jeff Rickard</p> <p>Well Number: 05-123-15598</p> <p>Inspection Document #:674103930</p> <p>Nature of complaint: Noise, Odor, Dust</p> <p>If Sound GPS Coordinates of Survey Location:NA</p> <p>Inspection Observations:</p> <p>An inspection of the above location was conducted with focus on noise, odor and dust. It was observed that Anadarko is upgrading/replacing the battery at the location. The old equipment is being hauled out and new equipment is being hauled in. The new equipment includes Tanks, Separators, and ECD's. OGCC inspector did observe dust coming from lease road when trucks drove on it, but did not observe any rule violations related to maintenance or storm water of the access road or location. The nearest NOAA weather station recorded wind gusts of 71mph today and winds still continue to be high which accounts for the dust being kicked up. No odors were observed by OGCC staff at time of inspection.</p> <p>18A DOC#200441076</p> | rickardj | 02/10/2017 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 401207847 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4073264 |