

Inspection Photos
Location Name: West Animas-University 9-3
API: 05-067-08741



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the northern portion of the working area from the northwestern corner facing eastward.

Inspection Photos
Location Name: West Animas-University 9-3
API: 05-067-08741



Photo 3. View of the northern portion of the interim reclamation area from the northwestern corner facing eastward. Revegetation is progressing with western wheatgrass (*Pascopyrum smithii*), intermediate wheatgrass (*Thinopyron intermedium*), and rubber rabbitbrush (*Chrysothamnus nauseosus*).



Photo 4. View of the western portion of the interim reclamation area. A vegetated silt trap is in good condition.

Inspection Photos
Location Name: West Animas-University 9-3
API: 05-067-08741



Photo 5. View of Scotch thistles (*Onopordum acanthium*) from the previous growing season in the northern portion of the interim reclamation area.



Photo 6. View of Scotch thistle rosettes in the eastern portion of the interim reclamation area.