



**photo 1:** Facing southwest along the access road. There are areas where the two track road is still visible.



**photo 2:** Pipe risers remain at the location.





**photo 3:** The area around the pipe risers is devoid of vegetation.



**photo 4:** Facing west toward the surrounding undisturbed vegetation.