

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/14/2017

Submitted Date:

02/14/2017

Document Number:

680401133**FIELD INSPECTION FORM**

Loc ID 312691 Inspector Name: BROWNING, CHUCK On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100185
 Name of Operator: ENCANA OIL & GAS (USA) INC
 Address: 370 17TH ST STE 1700
 City: DENVER State: CO Zip: 80202-

Findings:

- 4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271694	WELL	SI	07/08/2008	DSPW	077-08801	ORCHARD FEDERAL DISPOSAL 1	AC

General Comment:

Routine UIC inspection. MIT due by 4/4/2017.

Location

Lease Road:			
	Type	Access	
	comment:		
	Corrective Action		Date:
	Type	Main	
	comment:		
	Corrective Action		Date:

Overall Good:

Signs/Marker:			
	Type	TANK LABELS/PLACARDS	
	Comment:		
	Corrective Action:		Date:
	Type	WELLHEAD	
	Comment:		
	Corrective Action:		Date:

Emergency Contact Number:			
	Comment:	<input style="width: 95%;" type="text"/>	
	Corrective Action:	<input style="width: 95%;" type="text"/>	Date: _____

Overall Good:

Spills:			
Type	Area	Volume	
In Containment: No			
	Comment:	<input style="width: 95%;" type="text"/>	
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
	Type	LOCATION	
	Comment:		
	Corrective Action:		Date:

Venting:			
	Yes/No	NO	
	Comment:		
	Corrective Action:		Date:

Flaring:			
Type			
	Comment:		
	Corrective Action:		Date:

Inspected Facilities

Facility ID: 271694 Type: WELL API Number: 077-08801 Status: SI Insp. Status: AC

Underground Injection Control

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg 583 Previous Test Pressure _____ MPP _____
(e.g. 30 psig or -30" Hg) Inj Zone: WMFK
TC: Pressure or inches of Hg 2 Previous Test Pressure _____ Last MIT: 04/04/2012
Brhd: Pressure or inches of Hg 20 Previous Test Pressure _____ AnnMTReq: _____

Comment: Routine UIC inspection. Active injection at time of inspection.
MIT due by 4/4/2017

Corrective Action: _____ Date: _____

Method of Injection: PUMP FEED

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
MIT due by 4/4/2017.	browninc	02/14/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401210544	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4075620