

From: Burn - DNR, Diana [mailto:diana.burn@state.co.us]

Sent: Saturday, February 18, 2017 1:11 PM

To: Ty Entenmann <tentenmann@extractionog.com>

Cc: Kamrin Ruder <kruder@extractionog.com>; Garrison, Penny <penny.garrison@state.co.us>; Steve Jenkins <steve.jenkins@state.co.us>; Barbara Westerdale <barbara.westerdale@state.co.us>

Subject: Re: Sidetrack TC Country Club 5-9-11

Please call also - I am not always checking email on the weekend.

Please proceed as proposed.

Monday is a holiday for us.

Thanks,
Diana

On Feb 18, 2017 7:28 AM, "Ty Entenmann" <tentenmann@extractionog.com> wrote:

Diana,

We were on the TC Country Club 5-9-11 and had a collision issue with an offset surface well on the same pad. We didn't believe it was possible to miss this well bore with our angle and the separation at the moment (1-2'). We were at 600' and though we could do a better job of avoiding it next time with the gyro.

With your permission we would like to cement the well back to the conductor and try to drill it again with the assistance of a gyro until we can gain enough separation to avoid the well.

API # - 05-123-43508-00

Total MD Drilled – 600'

Surface Casing – hasn't been set yet

Proposed Fish – None

Open hole sidetrack plan: drill out of conductor again and start fresh

Depth of Sidetrack- at Conductor

Objective formation of sidetrack – Codell (same as APD)

Proposed BHL – Sec 11 – TWP 5N 66W 2247 FSL 2487 FEL (same as approved)

Thanks and please call with any questions,



Ty Entenmann

Drilling Engineer

Extraction Oil & Gas

370 17th St, Suite 5300

Denver, CO 80202

Direct: [720.557.8326](tel:720.557.8326)

www.ExtractionOG.com