

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/17/2017

Submitted Date:

02/21/2017

Document Number:

685302210**FIELD INSPECTION FORM**Loc ID 306765 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☐
- FOLLOW UP INSPECTION REQUIRED
- 
- ☒
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, All		SanJuanCOGCC@bp.com	<a href="#">SW Inspection Reports</a>
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	<a href="#">SW Inspection Reports</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
263435	WELL	PR	04/30/2002	GW	067-08720	HOLMAN CANYON 2	PR

**General Comment:**[See link at end of report for path to downloadable pictures.](#)

Inspected Facilities									
Facility ID:	263435	Type:	WELL	API Number:	067-08720	Status:	PR	Insp. Status:	PR

--

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Compaction	Pass	Ditches	Pass			
Sediment Traps	Pass					
Ditches	Pass	Gravel	Pass			
Berms	Pass	Check Dams	Pass	Material Handling And Spill Prevention	Pass	Berm around produced water tank.
Rip Rap	Pass					

Comment: [Corrective action completed.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685302225	Rip Rap installed at entrance	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4080753">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4080753</a>
685302226	Erosion repair at S end of location	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4080754">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4080754</a>
685302227	Closer view of erosion repair at S end of location	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4080755">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4080755</a>
685302228	Rip Rap on fill slope repair on S end of location	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4080756">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4080756</a>