

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/17/2017

Submitted Date:

02/22/2017

Document Number:

674901478**FIELD INSPECTION FORM**

Loc ID 333774 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 26625Name of Operator: ELM RIDGE EXPLORATION COMPANY LLCAddress: 12225 GREENVILLE AVE STE 950City: DALLAS State: TX Zip: 75243-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Archuleta, Amy		aarchuleta@elmridge.net	SW Inspection Reports
Lindeman, Terry	505-632-8048 EXT 210	tlindeman@elmridge.net	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290036	WELL	PR	04/08/2011	GW	067-09348	IGW 119	EI

General Comment:

On February 17, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Elm Ridge Exploration Company IGW #119. For the most recent field inspection report of this facility, please refer to document #674601242.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Free standing sign near well head.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:				
Type	Area	Volume		
Lube Oil	Pump Jack	<= 1 bbl		
Comment:	Impacted material beneath prime mover.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.			Date: 03/22/2017

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Fencing around perimeter of secondary containment berm.		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Guard fencing.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Concrete pad and soil underneath prime mover are stained.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 60		Date: 03/22/2017
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	500 BBLS	STEEL AST		37.120710,-107.763216

Comment:		
Corrective Action:		Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	290036	Type:	WELL	API Number:	067-09348	Status:	PR	Insp. Status:	EI

--

Environmental

Spills/Releases:

Type of Spill: _____	Estimated Spill Volume: _____
Comment: _____	
Corrective Action: _____	Date: _____
Reportable: _____	GPS: Lat _____ Long _____
Proximity to Surface Water: _____	Depth to Ground Water: _____

Water Well Complaint:

		Lat	Long
DWR Receipt Num: _____	Owner Name: _____	GPS : _____	_____

Field Parameters:

Sample Location: _____	Comment: _____
------------------------	----------------

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On February 17, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Elm Ridge Exploration Company IGW #119. For the most recent field inspection report of this facility, please refer to document #674601242.	hughesj	02/22/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674901479	Impacted material beneath prime mover.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4081628
674901480	Stained concrete pad and gravel.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4081629