

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/17/2017

Submitted Date:

02/22/2017

Document Number:

674901481

FIELD INSPECTION FORM

Loc ID 325165 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 26625
 Name of Operator: ELM RIDGE EXPLORATION COMPANY LLC
 Address: 12225 GREENVILLE AVE STE 950
 City: DALLAS State: TX Zip: 75243-

Findings:

- 8 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Archuleta, Amy		aarchuleta@elmridge.net	SW Inspection Reports
Fischer, Alex		alex.fischer@state.co.us	
Lindeman, Terry	505-632-8048 EXT 210	tlindeman@elmridge.net	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214181	WELL	PR	10/01/2013	GW	067-05501	MILLER MESAVERDE UNIT 1	EI

General Comment:

On February 17, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Elm Ridge Exploration Company Miller MV #1. For the most recent field inspection report of this facility, please refer to document #674600708.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Free standing sign near well head.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>	Date:	

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Steel beam laying along east side of location.		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	03/22/2017

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type				corrective date
Gas Meter Run	# 1			
Comment:				
Corrective Action:		Date:		
Deadman # & Marked	# 2			
Comment:	Only northern two rig anchor markers were observed.			
Corrective Action:		Date:		
Horizontal Separator	# 1			
Comment:				
Corrective Action:		Date:		

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	Open Top		37.128447,-107.755605
Comment:	Expanded metal cover. Tank is rusted along bottom and sides.				
Corrective Action:		Date:			

Paint

Condition	Inadequate	
Other (Content)		
Other (Capacity)	20 bbl.	
Other (Type)		

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:		
Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 214181 Type: WELL API Number: 067-05501 Status: PR Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Gravel	Pass			

Comment: Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
On February 17, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Elm Ridge Exploration Company Miller MV #1. For the most recent field inspection report of this facility, please refer to document #674600708.	hughesj	02/22/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674901482	Western side of location.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4081721
674901483	20 bbl. PW open topped tank.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4081722
674901484	Steel beam along eastern edge of location.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4081723