

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/22/2017

Submitted Date:

02/22/2017

Document Number:

685502050**FIELD INSPECTION FORM**Loc ID 320128 Inspector Name: MONTOYA, JOHN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10261Name of Operator: BAYSWATER EXPLORATION AND PRODUCTION LLCAddress: 730 17TH ST STE 610City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
BLYTH, TOM	303-893-2503	Tblyth@bayswater.us	Inspections
MacLaren, Joe		joe.maclaren@state.co.us	
Canfield, Chris		chris.canfield@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202755	WELL	PR	07/03/1982	OW	001-08160	ANDERSON 5	SI

General Comment:

Location

Lease Road:			
Type	Main		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: OK

Corrective Action:

Date: _____

Overall Good: ☒

Spills:					
Type	Area	Volume			
Crude Oil	Tank	>= 5 bbls			
Comment:	OIL SPILL AT WEST TANK UNDERNAETH WHERE PLUMB BOB HITS BOTTOM OF TANK				
Corrective Action:	Remove free fluids and contact COGCC EPS staff per Rule 906.b. 72 HOURS TO CLEAN UP SPILL				Date: 03/01/2017

In Containment: Yes

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 202755 Type: WELL API Number: 001-08160 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: OIL SPILL AT BATTERY

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
SPILL WAS CAUSED BY LEAK WHERE PLUMB BOB HITS BOTTOM OF TANK, APPTROX 120 BBLs OIL	montoyaj	02/22/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685502051	BATTERY SIGN	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4081990
685502052	LOOKING EAST SPILL AROUND WATER TANK	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4081991
685502053	EAST SIDE LOOKING AT EAST PROD TANK	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4081992
685502054	WEST SIDE LOOKING EAST, TANK LEAKING	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4081993
685502055	WEST PROD TANK LOOKING EAST	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4081994
685502056	SOUTH SIDE OF TANKS LOOKING EAST	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4081995
685502057	LOOKING NORTH AT PROD TANK AND WATER TANK	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4081996