





photo 1: Facing north toward the location.



photo 2: Pipe riser remains at the location.



**photo 3:** Facing north at the location. The vegetation has not established.



**photo 4:** Facing east toward the location. The vegetation has not established.